



## RIVER MILE 10.9 REMOVAL ACTION CAPPING OPERATIONS WEEKLY STATUS REPORT


### Summary of capping operations for the week ending November 24, 2013

Capping operations, which began the week of November 11, 2013, are being monitored to ensure that air and water quality are maintained at acceptable levels. To monitor air quality, two mobile sampling stations are set up each morning adjacent to the capping operations. To monitor water quality, a number of sampling locations have been established as shown on the map below.

*All capping operations were conducted within acceptable air and water quality monitoring limits*


- **Area Where Cap's Active Layer Was Placed this Week: 82,376 square feet**
- **Area Where Cap's Active Layer Was Placed to Date: 120,601 square feet**  
(Approximately 64% of the area to be capped)


### Capping Progress to Date Shown in Green



## Real-Time Air and Water Quality Monitoring

(Times in which there was capping activity are shown in yellow)





Water Quality Monitoring Locations